


## TEMPORAL METAL (ALUMINIUM, IRON, COPPER) MONITORING AND EXCEEDENCES FROM VARIOUS LOCATIONS ALONG THE MACKENZIE RIVER



Source: Mackenzie River Basin State of the Aquatic Ecosystem Report 2003. Mackenzie River Basin Board 2004.

Source: Figure 3.2-7 from NWT Environmental Audit Status of the Environment Report, 2005